



Service Delivery Committee	Tuesday, 14 March 2023	Matter for Information and Decision
-----------------------------------	-------------------------------	--

Report Title: **Review of Town Centre Public Bins (2023)**

Report Author(s): **Zach Bradford (Safety & Resilience Officer) and Stuart Marbrook (Corporate Assets Manager)**

Purpose of Report:	The purpose of this report is to ensure the Service Delivery Committee can make an informed decision on either removing, repairing, or replacing the Town Centre Public Bins on Bell Street in Wigston.
Report Summary:	The Review of Town Centre Public Bins report is a summary of the current condition of the bins and an approximate cost to replace the bins (as set out in Paragraph 2).
Recommendation(s):	A. The metal style bins currently in place are removed or replaced as soon as is reasonably practicable. B. Retrofit suitable replacement lids for the damaged bins (subject to availability).
Senior Leadership, Head of Service, Manager, Officer and Other Contact(s):	David Gill (Head of Law and Democracy / Monitoring Officer) (0116) 257 2626 David.Gill@oadby-wigston.gov.uk Stuart Marbrook (Corporate Assets Manager) (0116) 257 2852 Stuart.Marbrook@oadby-wigston.gov.uk Zach Bradford (Safety & Resilience Officer) (0116) 257 2866 Zach.Bradford@oadby-wigston.gov.uk
Strategic Objectives:	Our Economy (SO3)
Vision and Values:	Not applicable
Report Implications:-	
Legal:	There are no implications directly arising from this report.
Financial:	There are no implications directly arising from this report.
Corporate Risk Management:	No corporate risk(s) identified
Equalities and Equalities Assessment (EA):	There are no implications arising from this report. EA not applicable
Human Rights:	There are no implications arising from this report.
Health and Safety:	There are no implications arising from this report.
Statutory Officers' Comments:-	

Head of Paid Service:	The report is satisfactory.
Chief Finance Officer:	The report is satisfactory.
Monitoring Officer:	The report is satisfactory.
Consultees:	None.
Background Papers:	None.
Appendices:	None.

1. Background

- 1.1 In total there are 7 'metal style' bins placed in various locations outside of the shops throughout Bell Street.
- 1.2 The current condition of these bins is poor, as of writing this report 4 of the 7 total bins are missing lids.
- 1.3 As per SO3, carrying out either of the recommendations below will ensure Bell Street remains an inviting place to visit.

2. Cost of Replacement or Removal

- 2.1 The total cost to remove the bins will be approximately £500.
- 2.2 The total cost to replace all of the bins like for like will be approximately £3,500.
- 2.3 The total cost to replace the bin lids is unknown, as the style and design may have been discontinued.

3. Recommendations

- 3.1 It is recommended that all the bins are removed or replaced as soon as is reasonably practicable.
- 3.2 Alternatively, the damaged bin lids could be replaced (subject to availability, although it is likely that the style and design may have been discontinued given the age of the bins).